




**HARTCROWSER**

Earth and Environmental Technologies

Division of Environment



Coeur d'Alene Field Office

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
Fax 206.328.5581  
Tel 206.324.9530

J-2296-07

October 7, 1996

Mr. Gregory A. Rapp  
Construction Services Manager  
Potlatch Corporation  
1100 Railroad Avenue  
P.O. Box 386  
St. Maries, Idaho 83861

Re: Second Quarter Performance Report for 1996  
Avery Landing Recovery System

Dear Mr. Rapp:

Hart Crowser is pleased to present the Second Quarter Performance Report for 1996 for the free product recovery system at the Avery Landing site. This letter report presents the second quarter groundwater elevation and product thickness measurements.

## GROUNDWATER AND PRODUCT QUARTERLY MONITORING

Four extraction wells (EW-1, EW-2, EW-3, and EW-4), four monitoring wells (HC-1, MW-4, MW-5, and MW-11), and two piezometers (P-1, and P-2) were monitored on September 11, 1996. The locations of the monitoring points have been indicated in previous quarterly monitoring reports. At each monitoring location, depth to product, product thickness, and depth to groundwater measurements were recorded. These measurements are presented with those of previous monitoring rounds in Table 1 at the end of the text. If a location indicated the presence of product but we were unable to obtain product-related measurements, it is indicated in Table 1 as a sheen in the depth to product column. The river elevation was also monitored by taking measurements and extrapolating between the river surface slope and corresponding datum.



Extraction wells with measurable product thicknesses were EW-3 and EW-4. Extraction well EW-4 had only a trace of product detected. EW-3 contained 0.95 foot of product. Wells HC-4 and MW-11 continue to have product present at 0.40 and 0.86 foot, respectively. Monitoring at EW-2 indicated a sheen but because of the thin layer of the product, a measurement was not obtained. Wells HC-1, MW-4, MW-5, and the piezometers did not indicate the presence of product.

The product pump in extraction well EW-3 was set too high and thus was not in full operation during the whole second quarter. We believe this may have contributed to the excess product thickness in and around the EW-3. Even though the product pump EW-3 was not in continuous operation during the quarter, based on evaluating the groundwater elevations completed during the second quarter, free product containment was attained at this location. The general trends observed during this round of monitoring were consistent with previous rounds.

## PROJECT SCHEDULE

Table 2 presents the project schedule for the remainder of 1996. As indicated, we will monitor and prepare one more Quarterly Performance Report and one Annual Report for 1996. If you should decide that any of these dates need to be altered, please let us know as soon as possible.

**Table 2 - Avery Landing Recovery System  
Remaining Project Schedule for 1996**

Remaining Schedule	Date
Conduct 3rd Quarter Monitoring	November 5, 1996
Submit 3rd Quarter Performance Report	December 12, 1996
Submit Annual Report	January 27, 1997

## LIMITATIONS

Work for this project was performed, and this letter prepared, in accordance with generally accepted professional practices for the nature and conditions of the work completed in the



Potlatch Corporation  
October 7, 1996

J-2296-07  
Page 3

same or similar location, at the time the work was performed. It is intended for the exclusive use of the Potlatch Corporation for specific application to the referenced property.

If additional information or clarification is required, please call Terry Montoya at (206) 324-9530.

Sincerely,

**HART CROWSER, INC.**

**TERRY MONTOYA**  
Project Engineer

**BARRY L. KELLEMS, P.E.**  
Associate

TM/BLK:sde  
229607\2ndqtr96.doc

Attachments:

Table 1 - Avery Landing Groundwater Monitoring Data

cc: Kreg Beck, Idaho Department of Environmental Quality



**Table 1 - Avery Landing Groundwater Monitoring Data**

Sheet 1 of 2

Monitoring Location	Date	Depth to Product	Depth to Water	Product Thickness	T.O.C. Elevation	Groundwater Elevation
EW-1	10/27/94	ND	11	0	95.34	84.34
	6/30/95	ND	10.9	0	95.34	84.44
	9/21/95	11.25	11.27	0.02	95.34	84.07
	7/11/96	ND	9.74	0	95.34	85.60
	9/11/96	ND	10.88	0	95.34	84.46
EW-2	10/27/94	ND	10.37	0	95.24	84.87
	6/30/95	10.57	10.89	0.32	95.24	84.35
	9/21/95	13.9	13.92	0.02	95.24	81.32
	7/11/96	11.03	11.66	0.63	95.24	83.58
	9/11/96	Sheen	14.00	0	95.24	81.24
EW-3	10/27/94	ND	10.05	0	95.78	85.73
	6/30/95	9.35	9.8	0.45	95.78	85.98
	9/21/95	10.92	11.08+	0.16	95.78	84.70
	7/11/96	8.53	8.64	0.11	95.78	87.14
	9/11/96	10.75	11.70	0.95	95.78	84.08
EW-4	10/27/94	ND	8.05	0	94.32	86.27
	6/30/95	7.84	7.85	0.01	94.32	86.47
	9/21/95	8.22	8.24	0.02	94.32	86.08
	7/11/96	Sheen	6.44	0	94.32	87.88
	9/11/96	ND	8.42	0	94.32	85.90
HC-1	10/27/94	ND	13.25	0	97.50	84.25
	6/30/95	ND	12.00	0	97.50	85.50
	9/21/95	NM	13.42	0	97.50	84.08
	7/11/96	ND	11.92	0	97.50	85.58
	9/11/96	ND	12.90	0	97.50	84.60
HC-4	10/27/94	13.3	15.34	2.04	98.94	83.60
	6/30/95	11.89	15.49	3.6	98.94	83.45
	9/21/95	13.67	NM	NM	98.94	85.27
	7/11/96	11.58	12.93	1.35	98.94	86.01
	9/11/96	13.53	13.93	0.40	98.94	85.01
MW-4	9/14/94	ND	12.88	0	99.76	86.88
	6/30/95	ND	10.19	0	99.76	89.57
	9/21/95	ND	11.95	0	99.76	87.81
	7/11/96	Sheen	10.18	0	99.76	89.58
	9/11/96	Sheen	11.33	0	99.76	88.43
MW-5	10/27/94	ND	10.45	0	97.76	87.31
	6/30/95	ND	9.13	0	97.76	88.63
	9/21/95	ND	10.83	0	97.76	86.93
	7/11/96	ND	8.98	0	97.76	88.78
	9/11/96	ND	10.71	0	97.76	87.05
MW-11	9/14/94	12	NA	NA	98.16	NA
	6/30/95	5.54	7.25	1.71	98.16	90.41
	7/11/96	6.34	10.00	3.66	98.16	88.16
	9/11/96	6.34	7.20	0.86	98.16	90.96

**Table 1 - Avery Landing Groundwater Monitoring Data**

Sheet 2 of 2

Monitoring Location	Date	Depth to Product	Depth to Water	Product Thickness	T.O.C. Elevation	Groundwater Elevation
P-1	10/27/94	ND	17.31	0	101.42	84.11
	6/30/95	ND	16.72	0	101.42	84.70
	9/21/95	ND	17.4	0	101.42	84.02
	7/11/96	ND	15.87	0	101.42	85.55
	9/11/96	ND	16.98	0	101.42	84.44
P-2	10/27/94	ND	15.87	0	100.06	84.19
	1/0/00	ND	15.26	0	100.06	84.80
	9/21/95	ND	16.04	0	100.06	84.02
	7/11/96	ND	14.52	0	100.06	85.54
	9/11/96	ND	15.62	0	100.06	84.44
River EW-1	10/27/94					83.12 *
	6/30/95					84.03 **
	9/21/95					82.24
	7/11/96					83.74 ***
	9/11/96					82.56 ***
River EW-2	10/27/94					84.41
	6/30/95					85.32
	9/21/95					83.53
	7/11/96					85.03
	9/11/96					83.85
River EW-3	10/27/94					85.16 *
	6/30/95					86.07
	9/21/95					84.28
	7/11/96					85.78 ***
	9/11/96					84.60 ***
River EW-4	10/27/94					86.49 *
	6/30/95					87.40
	9/21/95					85.61
	7/11/96					87.11 ***
	9/11/96					85.93 ***

All measurements in feet.

\* River elevation was extrapolated from the river surface slope measured in 1995 and the river elevation measured south of EW-2 in 1994.

\*\* River elevation was extrapolated from river surface slope, based on river elevations measured south of EW-2, EW-3, and EW-4 in 1995.

\*\*\* River elevation was extrapolated from river surface slope, and the wood dock benchmark

ND - Not Detected  
NA - Not Available  
NM - Not Measured